
<u>SYMBOL</u>

<u>REFERENCE</u>

WET UTILITY LEGEND



MATCHLINE - SEE SHEET C-3.2

| | STORM | | | | |
|-----|----------------|---------|----------------------|-----------|-------|
| (5) | BEARING | LENGTH | SLOPE | SIZE/TYPE | |
| 1 | N 90°00'00" E | 71.36' | -1.0% 0.8 | 4% 8" PVC | 1 |
| | N 07°17'01" W | | 1 007 | o" DVC | / \ |
| | 14 07 10 21 11 | 71.27 | 1.070 | 0 1 10 | |
| 3 | N 12°39'37" E | 22.70' | 1.0% | 8" PVC | |
| 4 | N 89°46'20" E | 32.63' | 1.0% | 6" PVC | |
| 5 | N 00°13'40" E | 106.00' | 1.0% | 6" PVC | |
| 6 | N 00°13'40" E | 71.25 | 1.0% | 6"PVC | |


SPECIAL NOTES FOR MIRAMAR COLLEGE:
THE FOLLOWING NOTES PROVIDED BY THE DISTRICT FOR CONTRACTOR REFERENCE:

CAUTION:

1. THE CONTRACTOR MAY ENCOUNTER OLD MILITARY ORDNANCE. THE CONTRACTOR SHALL NOTIFY THE DISTRICT IMMEDIATELY IF THEY ENCOUNTER ANY ORDNANCE.

2. GEOTECHNICAL INVESTIGATIONS FOR THE SURROUNDING IMPROVEMENTS DESCRIBE THE UNDERLYING SOILS AS SANDY CLAY OVER HIGHLY CEMENTED GRAVEL AND COBBLE CONGLOMERATE (LINDA VISTA FORMATION AND STADIUM CONGLOMERATE). NO GROUNDWATER WAS ENCOUNTERED. TRENCHING INTO THE LINDA VISTA FORMATION AND STADIUM CONGLOMERATE WILL BE DIFFICULT AND MAY REQUIRE HEAVY EQUIPMENT.





| .S.A. | DISTRICT ARCHITECT |
|-------|--------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

APPROVED BY

APPROVED BY

CHECKED

JHS

REVISION

1

DRAWN

MIRAMAR COLLEGE
INFRASTRUCTURE AND SITE
DEVELOPMENT PHASE II (SOUTH)
SCOPE "B"

SAN DIEGO COMMUNITY COLLEGE DISTRICT

AUGUST 3, 2017

SHEET 12

C-3.1

of **46**

IIRAMAR SCOPE B\CADD\LAND\DLV\SCOPE B\130852-UT-01-B.DWG PITTMAN, KAYSIE 3/11,

